

Search

Products



Home > Downloads >

Green Products

Promotion



Downloads

Motherboards

AK77-600GN

Category

OrderBy:


ReleasedDate

Advanced Search

:: Selection: Motherboards >> AK77-600GN >>

:: The Latest Releases: 38 records

Category	Software / Description	Version	ReleaseDate	Download
AK77-600GN				
BIOS	<ul style="list-style-type: none"> Fixed MEMTEST-86 utility test failed while plug AMD FSB 200 CPU. Added "OnChip SATA" item in the "Integrated Peripherals" page to disabled/enabled onboard SATA controller. 	R1.08	12/15/2004	407.8 KB
OS Support: DOS, Win2000, Win98SE, WinME, WinXP				
	<ul style="list-style-type: none"> Supported AMD Sempron Model 10 (CPUID = 6A0H) CPUs. 	R1.07	11/10/2004	407.7 KB
OS Support: DOS, Win2000, Win98SE, WinME, WinXP				
	<ul style="list-style-type: none"> Supported AMD Sempron processor. 	R1.06	7/14/2004	407.7 KB
OS Support: DOS, Win2000, Win98SE, WinME, WinXP				
Driver	Realtek RTL8139/810x NIC Driver <ul style="list-style-type: none"> Realtek Lan driver for win98se/me/2000/XP 	R5.05	3/6/2004	2140.0 KB
OS Support: Win2000, Win98SE, WinME, WinXP				
	VIA SATA Driver <ul style="list-style-type: none"> VIA Serial ATA Driver 	R1.00d	2/25/2004	6377.7 KB
OS Support: Win2000, Win98SE, WinME, WinXP				
BIOS	<ul style="list-style-type: none"> Fixed BIOS hanged up 'C1' after clear CMOS. Fixed USB Keyboard or mouse device plugged in USB jack that cause S1/S3/S4 into suspend fail. 	R1.04	2/13/2004	407.4 KB
OS Support: DOS, Win2000, Win98SE, WinME, WinXP				
Utility	EzSkin Utility <ul style="list-style-type: none"> EZSkin utility 	V2.00.03	12/25/2003	1138.4 KB
OS Support: Win2000, Win98SE, WinME, WinXP				
	AOpenConfig Utility <ul style="list-style-type: none"> AOpenConfig utility is for Windows 98SE/ME/2000/XP/NT 	V2.00.06	12/25/2003	773.7 KB
OS Support: Win2000, Win98SE, WinME, WinXP				
BIOS	<ul style="list-style-type: none"> Fixed reseted again issued with some VGA cards, When you pushed power button on. 	R1.02	12/13/2003	407.1 KB
OS Support: DOS, Win2000, Win98SE, WinME, WinXP				

- checksum: E8A6H
- Changed VT8237 SATA Option ROM From "6420R120.ROM" to "6420R201.ROM"
- Implemented to supported VGA nVidia MX440i/BMX420i/BFX5200 PCI Cards to entry WinXP.
- Modified "Clock Spread Spectrum" in "Frequency/Voltage Control" Page default value from "Enabled" to "Disabled"  438.0 KB
- Supports Duron(tm) 1400MHz FSB133 CPU.
- Modified "5VSB(V)" in "Silent BIOS/HW Monitor" Page to more exactly.

OS Support: Win2000, Win98, Win98SE, WinME, WinNT, WinXP

1 2 3 4

[Back to Downloads](#)

[Page Top](#)